

FORD DOOR TRIGGER ISOLATION Diagram:

This Diagram applies to Ford vehicles with Body Control Modules that shut down after the doors are locked and can cause false alarms from the Door or Rear Hatch/Trunk input Triggers. When Body Control Modules shut down to save power, there is change of state on the door triggers wires that an Alarm will see as a false trigger. Isolating the door pin switch wires using this diagram will eliminate the false alarms. Use 1 Amp general purpose Diodes, part # 1N4001

EXAMPLE:

